

























- 1. What is this? Chinese microfeeder; variable speed driver; on/of mechanism not consistent; poor internal mixing; low price (500 dollar)
- 2. Nice microfeeders (25000 dollars): what is wrong? placed at the end of the screw conveyer!
- 3. What is wrong? Microfeeder (10.000 dollar): will you walk up this ladder with a bag of 25 kg? -> not easily accessible
- 4. What is the wrong? Similar as 3 but other mill
- 5. What is wrong? Nothing! Good ladder and platform is present
- 6. What is wrong? Again, not right place: pipework all around; homemade microfeeder; => go up to the floor of the plansifers (however, not to close to the plansifer); you can go up to 3 floors.
- 7. Something wrong? You cannot easily tell: connected to the aspiration system for dust, premix is sucked away (QA/QC is compliant however; risk should have been assessed for in risk analysis)
- 8. Something wrong? Nothing
- 9. Mill on truck: 'undercover mill'